

PERFORMANCE RESULTS

Kingspan Environmental part of
which is **Envirocare Pollution Control**
College Road North, Aston Clinton Dundalk Road, Carrickmacross
Aylesbury, Buckinghamshire, HP22 Co Monaghan Ireland
5EW, Great Britain

EN 12566-1

Part 1: Prefabricated septic tanks

Results corresponding to the Irish National Annex for IS EN 12566-1

Beta+ Septic Tank

Material	polyethylene
Durability	pass
Crushing resistance (pit test)	pass (dry conditions)
Watertightness (water test)	pass
Nominal capacity (usable volume) (water test)	3 m ³ (3,221 l), 4 m ³ (4,224 l)
Hydraulic efficiency (Annex B)	99.65 %

Performance tested by:

PIA – Prüfinstitut für Abwassertechnik GmbH
(PIA GmbH)
Hergenrather Weg 30
D-52074 Aachen

Certified according to
ISO 9001:2008



Notified Body number: 1739



This document replaces neither the declaration
of conformity nor the CE marking.

Prüfinstitut für Abwassertechnik GmbH
Elmar Lancé
Geprüft - tested - testé

Elmar Lancé

March 2012

PERFORMANCE RESULTS

Kingspan Environmental
College Road North, Aston Clinton
Aylesbury, Buckinghamshire, HP22
5EW, Great Britain

part of
which is

Klargester Ireland
Unit 1, Derryboy Road , Carnbane
Industrial Estate, Newry,
Co. Down, BT35 6QH, UK

EN 12566-1

Part 1: Prefabricated septic tanks

Results corresponding to the Irish National Annex for IS EN 12566-1

Beta+ Septic Tank

Material	polyethylene
Durability	pass
Crushing resistance (pit test)	pass (dry conditions)
Watertightness (water test)	pass
Nominal capacity (usable volume) (water test)	3 m ³ (3,221 l), 4 m ³ (4,224 l)
Hydraulic efficiency (Annex B)	99.65 %

Performance tested by:

PIA – Prüfinstitut für Abwassertechnik GmbH
(PIA GmbH)
Hergenrather Weg 30
D-52074 Aachen

Certified according to
ISO 9001:2008



Notified Body number: 1739 

This document replaces neither the declaration
of conformity nor the CE marking.

Prüfinstitut für Abwassertechnik GmbH

geprüft - tested - teste

Elmar Lancé

March 2012